FIELD INSPECTION REPORT

	X 4 6 3 4 5 1		
D 4 . CI	nspection: 01-01-20 Di	strict: Roktas	
Date of I	e RwD(w) division, Sasaron -1 Le	ength (km): 3.525	
Division	the Road: Karaglar Pontitional Ke A	Extitor the Gount to help to	Ra Hirman
Name of	Programme: MAINTENANCE	0.000 1 8 1 8 1 8 1 8 1 8 1 8 1 8 1 8 1 8	
Package	No. 213 CS4 R	ond Id No.:	
	the Bestact: Oneoing/Completed/Ur	der Maintenance	
	a case of: New Connectivity/Up g	radation/ Maintenance	
SI. No.	Parameters to be	checked	Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		V S/U
	Road Camber		Jsru
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No.
g)	Compaction of flank/slope & raincuts if any		/Yes/No
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		-S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		_S/SRI/U
c)	Condition of railings/slab/approach for Bridges		_ S/SRI/L
. 3.	Road Purniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.4	Complianes Elistory		**
8)	Status of ATR's & any others		1-10

Overall Rating

Satisfactory (S)	`\$'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Makest Possed Sal

DESIGNATION: 3 E