

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020	District: Buxar
Division : RWD, Dumraon	Length (km):
Name of the Road: Bhadwar NH30 path ke prathamik vidhyalaya Kodhi Noniya to mod to badadhi mughar toli tak	
Scheme/Programme:	MAINTENANCE mmGsy (WB)
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ☒
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

main Sign board required repainting

NAME:

DESIGNATION:

Akshay
21/12/2020
JE

A2
21/12/20
AC

(Signature)