FIELD INSPECTION REPORT

Date of Inspection: 26.12.2020 District: Buxe			District: Buxar		
K-W-D Dum-			Length (km): 2.00 KM		
-	me Road: D	Cap Khurd	but to mukund dera	Paschi	
scheme/	Programme:	MAINTENANCE	<u> </u>		
Package Status of	No.: (the Project:		Road Id No.:		
Work is	a case of:		Up gradation/ Maintenance		
Sl. No.		Parameters to	and the same of th	Remarks	
1.	Pavement	3. 5. 1	and the second s	and the little of the little o	
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			WU SHU	
c)	Riding Quality			√S/U	
d)	Road Camber			√8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No.	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina	ige		HIND SHE	
a)	Condition of head walls in Hume pipe culverts including its painting			8/SRI'U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
e)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No.	
4.	Compliance History			10 17 18 18 18 18 18 18 18 18 18 18 18 18 18	
a)	Status of ATF	e's & any others	Control of the Property of the Control of the Contr	1	

Overall Rating

14 Table 1 Table 1

Moberationes

	A STATE OF THE PARTY OF THE PAR
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	605
Unsatisfactory (U)	SRI

20 12 20 20 20 12 20 20

(Signature)

NAME:

CS Scanned with