

# FIELD INSPECTION REPORT

|                                                                 |                      |
|-----------------------------------------------------------------|----------------------|
| Date of Inspection : 29.12.2020                                 | District: Buxar.     |
| Division : R.W.D. Dumraon                                       | Length (km): 0.700 M |
| Name of the Road: Adimi Biswa road to Kapidehu.                 |                      |
| Scheme/Programme: MAINTENANCE ✓                                 |                      |
| Package No.:                                                    | Road Id No.:         |
| Status of the Project: Ongoing/Completed/Under Maintenance ✓    |                      |
| Work is a case of: New Connectivity/Up gradation/ Maintenance ✓ |                      |

| S. No. | Parameters to be checked                                                                                             | Remarks     |
|--------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.     | <b>Pavement</b>                                                                                                      |             |
| a)     | Road Junction condition                                                                                              | ✓ S/U       |
| b)     | Condition of Surfacing                                                                                               | ✓ S/U       |
| c)     | Riding Quality                                                                                                       | ✓ S/U       |
| d)     | Road Camber                                                                                                          | S/U         |
| e)     | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No    |
| f)     | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No    |
| g)     | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No    |
| 2.     | <b>Cross Drainage</b>                                                                                                |             |
| a)     | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U   |
| b)     | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U N/A |
| c)     | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U N/A |
| 3.     | <b>Road Furniture</b>                                                                                                |             |
| a)     | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓    |
| 4.     | <b>Compliance History</b>                                                                                            |             |
| a)     | Status of ATR's & any others                                                                                         | -           |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

*Handwritten signature and date: 29/12/2020*

(Signature)

NAME:

DESIGNATION: