

प्रमाणित किया जाता है कि इस मापी-
 पुल में मशीन द्वारा अंकित कुल
 100 (एक सौ) पन्ने हैं, जिमें M.M.G.
 S.Y. (S.C.) मद अन्तर्गत सेवरा दुर्गा-
 वती बाँध से देवरा पत्र का मापी
 लेने हेतु श्री रामचन्द्र पंडित, सहा
 आभ कार्य अवट प्रमंडल कुदरा के
 नाम पर निर्गमित किया जाता है)

कार्यपालक अभियंता
 जलान कंठ विभाग
 कार्यपालक, मोरनिवा
 13/5/20

Revised to JE
 H. H. H.
 13/5/20
 H.

M.M.G.S.Y. S.C.
 Sch. XLV—Form No. 134

कार्य अवट प्रमंडल कुदरा DIVISION
 श्री रामचन्द्र पंडित, सहा आभ SUBDIVISION
 पत्र - सेवरा दुर्गावती बाँध से देवरा पत्र
 संवेदक - जय बजरंग कंठ
 एक्यरनामा - 135BD/11.5.20

Measurement Book

No. 418
 20-21

Name of Officer _____

Date of first entry _____

Date of last entry _____

Name to work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
1st and on A/C Bill					
CH-IMGSY					
M/W! Construction of Road					
From ^{New} Durgawati Branch					
To Dewa Path.					
Agency! - m/s Jai Bajrang					
Construction					
Date of start 11/5/20					

Date of Completion 10/5/21				
Date of Actual				
Completion! work in				
Progress				

① clearing and grubbing
Road land do
all complete

$10 \times 30.00 \times 3.50 = 1050.00 \text{ m}^2$	
$10 \times 30.00 \times 3.50 = 1050.00 \text{ m}^2$	
$10 \times 30.00 \times 3.50 = 1050.00$	
$10 \times 30.00 \times 3.50 = 1050.00$	
$5 \times 30.00 \times 3.50 = 525.00$	

Continuation

7725.00

= 0.4725 Hekt

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2.96 m ³ qty used P-31					
					cu 5700 = 65/m ³ 168732
(12/25) Poor Broken masonry work in cm (1.4) in head wall & sill					
30.606 m ³ qty used P-31					
					cu 6342 = 78/m ³ 194127
(13/26) Poor and large R.C.C. Pipe MP3 for culvert on 1st class bedding of P.C.C. in single row 1000 mm dia					
7.80 m ³ qty used P-31					
					cu 3549 = 46/m ³ 266212
(14/27) plaster work on front of Mortar (1.4) on broken work in Superstructure.					
66.85 m ³ qty used P-31					
					cu 330 = 94/m ³ 22123

Continuation

M 62222862

[illegible]

Continuation

Continuation
Only 20 HMOY
22/12/20
AL