

## FIELD INSPECTION REPORT

Date of Inspection : 25/12/2020		District : Purnea
Division : Purnea		Length (Km) : 1.469
Name of the Road : LO40 - To, to Bahua		
Scheme/Programme :	Maintenance	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
SL No	Parameters to be Checked	Remarks
<b>1).</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No
<b>2).</b>	<b>Cross Drainage</b>	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U NA
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U NA
<b>3).</b>	<b>Road Furniture</b>	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No
<b>4).</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)


Unsatisfactory (U)

SRI

Name : ROHA SARMA

Designation : PE

RWD, Works Division, Purnea.

  
 25/12/20  
 (Signature)