

# FIELD INSPECTION REPORT

Date of Inspection : 04.01.2021		District : Katihar	
Division : Katihar		Length (Km) : 2.25	
Name of the Road : L121 - Dighri to Amirpur Hardas (VR)			
Scheme/Programme :		PMGSY I	
Package No. : BR 16 R 14 8		Road ID No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No	Parameters to be Checked		Remarks
1).	<b>Pavement</b>		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)		Yes/No NA
g)	Compaction of Flank/Slope & Raincuts if any		✓Yes/No
2).	<b>Cross Drainage</b>		
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U NA
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U NA
3).	<b>Road Furniture</b>		
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		✓Yes/No
4).	<b>Compliance History</b>		
a)	Status of ATR's & any others		NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name : CHANDRAHAS KUMAR  
 Designation : Executive Engineer  
 R.W.D. Works Division, Katihar.

  
 (Signature) 11/1/2021