## FIELD INSPECTION REPORT

Date of Inspection: 04.01.2021			District : Katihar	
Division : Katihar			Length (Km): 1.452_	
Name of the	Road: Imli Ch	owk to Kushwa	ha Tola	
Scheme/Programme:		MMGSY (ST)		
Package No. :			Road ID No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/Maintenance		
SI. No	Parameters to be Checked		Remarks	
1).	Pavement			
a)	Road Junction condition			S/U S
b)	Condition of Surfacing			S/U ح
c)	Riding Quality			S/U S
d)	Road Camber			کہ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No M/
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA
g)	Compaction of Flank/Slope & Raincuts if any			Yes/No S
2).	Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U ડ
<b>b</b> )	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U MA
c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U NA
3).	Road Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No '
4).	Compliance History			
a)	Status of ATR's & any others			NA
			·	<u>,</u>
Overall Rati	ng :	Satisfactory (S)		S
Satisfactory but requires Improvement (SRI)			mprovement (SRI)	
		I Importing Contours (III)		

Name:

CHANDRAHAS KUMAR

Degisnation: Executive Engineer R.W.D. Works Division, Katihar.

(Signature) 41172M