

FIELD INSPECTION REPORT

Date of Inspection :	31/12/2020	District :	Chitwan
Division :	Chitwan	Length (km):	0.990 km
Name of the Road:	Siddheshwari, Ems. Tola (near Sarda, Ch. 1.5) Bardha Tola, E.C. Ghada, Chitwan		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U-
b)	Condition of Surfacing		S/U-
c)	Riding Quality		S/U-
d)	Road Camber		S/U-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No-
f)	Contraction Joints provided or not (CC Pavement)		Yes/No-
g)	Compaction of flank/slope & raincuts if any		Yes/No-
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U-
c)	Condition of railings/slab/approach for Bridges		S/SRI/U-
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No-
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

[Signature]
31/12/2020
AE

[Signature]
31/12/2020
AE

(Signature)