FIELD INSPECTION REPORT

Date of I	Inspection: 20/12	120 District: AREIZ		
Name of Road:		S 067 बस्तील कुरेंडा पच वे हुँडे नी संघाली		
Scheme/	Programme:	MAINTENANCE MMUSY(SC)		
Package	No.	Road ID No.		
Status of the Project:		Onging/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance		
Sl.No	P. B. L.	Parameters to be Checked	Remarks	
1	Pavement			
a)	Road Junction Condition S/U			
b)	Condition of Surfacing		S/U	
c)	Riding Quality			
d)	Road Camber			
e)	Whether free from o	Yes/No		
f)	Contraction Joints provided or not (CC Pavement) Yes/No			
g)	Compaction of flank/slpoe & raincuts if any Yes/No			
2	Cross Drainage			
a)	Condition of headwalls inn Humepipe culverts including its painting S/SRI/			
b)	Condition of Abutment & Wings walls, Slab in RCC culverts			
c)	Condition of railings/slabs//approach for Bridges			
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			
4	Compliance History			
a)	Status of ATR & any others			
Overall Grading:		Satisfactory (S)	S	
Overall	Grading.	Satisfactory but requires Improvement(SRI)		
Overan	Grading.	Satisfactory but requires Improvement(SRI)		

Satisfactory (S)	S
Satisfactory but requires Improvement(SRI)	The second second
Unsatisfactory (U)	

Name: Ram chanda Ram Degisnation Junior Engineer (Signature)