FIELD INSPECTION REPORT

FIELD INSPECTION REPORT					
Date of Ins	pection: 🥞	District: Arang	7		
Division: Porbesgard .			District: Amana Length (km): 2.041 Kim		
Name of the Road; graft Basithi to humwants					
Scheme/Programme: MAINTENANCE			Road Id No.:		
Package No.:			Mular Maintenance		
Status of the Project:		Ongoing/Completed/Under Mnintenance New Connectivity/Up gradation/ Maintenance Remarks			
Work is a case of:		The same of the sa	In illieckon		
Sl. No.	The state of the s	Parameters se		6.01	
1	Pavement	and the second second	<u> </u>	S/U	
a)	Road Junction condition			, 8/U	
	Condition of Surfacing			S/U	
1 ' 1				S/U	
	Riding Quanty				
d)	c and defects such as visited				
e)	Whether free from derects aggregates in case of CC Pavement. Aggregates in case of CC Pavement)			Yes/No	
	Garageion Joints provided of not (60			Yes/No	
	Contraction of flank/slope & raincuts if any				
g)	Cross Drainage:				
4.3	Use Hume nine culvets more				
- i	S/SR			S/SRI/U	
b)	Condition of Abutiness Condition of railings/słab/approach for Bridges				
	the state of the s				
200	Roard/km & 20011 Yes/No			Yes/No	
a)	Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m Yes/I stones/Pavement road markings are provided and maintained				
4	Compliance History Ho				
a)	Status of ATR	's & any others			

Overall Rating

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	,
Unsatisfactory (U)	

(Signature)

NAME: Birdeshnown. prosael fam At Panigary