

FIELD INSPECTION REPORT

Date of Inspection : 18/12/20		District: Araria	
Division : Forbesganj		Length (km): 2.932-km	
Name of the Road: Phool Bashi Idgah to Mahadoli taln pahi Adarwallah			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		Remarks	
Work is a case of: New Connectivity/Up gradation/ Maintenance		Parameters to be checked	
Sl. No.			
1.	Pavement		✓S/U
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		S/SR/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		N/O
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Pradeep Kumar Prasad Ram
AE/Forbesganj

18/12/20
Pradeep Kumar Prasad Ram
(Signature)