

FIELD INSPECTION REPORT

Date of Inspection: 3-1-21	District: Chapra
Division: Chapra	Length (km): 1.60 km
Name of the Road: Chapra Buzurg to Harnadpur (Harnadpur to Chapra Buzurg)	
Scheme/Programme: MAINTENANCE	Work Id No.: 101634 (Sc)
Package No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: New Connectivity/Up gradation/ Maintenance	✓

for project
interlink

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	-S/U
b)	Condition of Surfacing	-S/U
c)	Riding Quality	-S/U
d)	Road Camber	-S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	✓ SRI
Unsatisfactory (U)	—

3/1/2021
62
Gurukul

(Signature)

NAME:

DESIGNATION: