FIELD INSPECTION REPORT

Date of In	enaction :		District: mman.	A COLUMN AND A STATE OF THE STA	
Division t	Mary 1016	Fast-2	Length (km): 1.082		a achaule
Name of t	he Rand: P. F	20 Sadak Se	Length (km): 1,082 Utraw Chank to Chi	engelmush	Day Oranic
Scheme/P	rogramme:	MAINTENANCE			*
Package ?			Road Id No.:		
	the Project:	Ongoing/Completed	/Under Maintenance		
Work is a		New Connectivity/U	Jp gradation/ Maintenance		
SI. No.		Parameters to	be checked	Remarks =	
1.	Pavement				
a)	Read Junction	condition		→S/U	
b)	Condition of	Surfacing		_S/U	
c) .	Riding Qualit	y		_S/U	
d)	Road Camber S/U				
c)	Whether fre	Whether free from defects such as visible cracks, exposed Yes/No ringgregates in case of CC Pavement.			
0		oints provided or not		Yes/No	
g)		of flank/slope & rain		Yes/No	
2.	Cross Drain	age			
78)	A CONTRACT OF THE PARTY OF THE		pipe culverts including its painting	S/SRI/U	
b)			valls, Slab in RCC culverts	S/SRI/U	
(c)	1	railings/slab/approac		S/SRI/U	
3.	Road Furni				
a)	Whether sig	gn boards/informato ment road markings a	ry/cautionary Board/km & 200n are provided and maintained	Yes/No	•
4.	Compliance	e History	VERTICAL TOTAL		
a)	Status of A'I	TR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	

This goal is blood effected.

Show

(Signature) -202

NAME: - Umshpagwan

DESIGNATION: - Junior Engineer.

Scanned with CamScanner