


## FIELD INSPECTION REPORT

Date of Inspection : 21/12/2020		District: Nalanda	
Division : Harnaut		Length (km): 0.90 km	
Name of the Road: Bagarpar Nahuntar PMGSY path to Nahuntar			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
<b>1.</b>	<b>Pavement</b>		
a)	Road Junction condition U	S/U	
b)	Condition of Surfacing U	S/U	
c)	Riding Quality U	S/U	
d)	Road Camber U	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. NO	Yes/No	
f)	Contraction Joints provided or not (CC Pavement) Yes	Yes/No	
g)	Compaction of flank/slope & raincuts if any NO	Yes/No	
<b>2.</b>	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting N/A	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges N/A	S/SRI/U	
<b>3.</b>	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained NO	Yes/No	
<b>4.</b>	<b>Compliance History</b>		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

  
 21/12/2020  
 (Signature)

NAME: RAVI KUMAR  
 DESIGNATION: Jr. Engineer

Scanned with CamScanner