

FIELD INSPECTION REPORT

Date of Inspection : 30/12/20		District: E. Champaran.
Division : Raxaul		Length (km): 1.512
Name of the Road: Shyampur Thakurani Tola Road to GSB Camp. Morita.		
Scheme/Programme: MAINTENANCE mm65Y(SC)		
Package No.:		Road Id No.: 31708513014
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary. Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:- CH. 1.05km to 1.512km crust damaged in Flood 2017, & 2019 rest part of road is in good condition.

[Signature]
30/12/20
(Signature)

NAME: Shashi Kant Singh
DESIGNATION: Junior Engineer