

# FIELD INSPECTION REPORT

Date of Inspection : 30/12/20		District: E. Champaran
Division : Raxaul		Length (km): 1.209
Name of the Road: MMGSY Road Kaboristan to Chikthapti Masjid		
Scheme/Programme: MAINTENANCE MMGSY (SC)		
Package No.:		Road Id No.: 31708513020
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary, Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

*Shashi Kant Singh*  
30/12/20  
(Signature)

NAME: Shashi Kant Singh

DESIGNATION: Junior Engineer