## FIELD INSPECTION REPORT

Date	of Inspection : -	0/11/01/2	District	•	
Date of Inspection: 30/14/20  Division: Raxall			District: E. Champoran.		
Name	of the Road: 97	10 0-10	Length (km): 1-10	-	
Schen	ne/Programme:	MAINTENANCE	Length (km): 1.10 So to Bordo Arvo MMG5Y (SL)	ri Tola.	
Packa	ge No.:	111111111111111111111111111111111111111	0,01		
Status	of the Project:	Ongoing/Completed	Road Id No.: 317085	3021	
Work is a case of:		Ongoing/Completed/Under Maintenance  New Connectivity/Up gradation/ Maintenance			
Sl. No	•	Parameters to 1			
1.	Pavement			Remarks	
a)	Road Junction	condition		manufa special manufacture and an	
b)	Condition of Surfacing			~5/U	
c)	Riding Quality			S/U-	
d)				S/U-	
<u>u,</u>	Road Camber S/U				
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)  Yes/No				
g)	Compaction of flank/slope & raincuts if any			1	
2.	Cross Drainage Yes/No				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing wells Class in D.C.				
c)	Condition of railings/slab/approach for Bridge				
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No	
7	Compliance Histo				
a) 5	Status of ATR's &	any others			
			i	1	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Shashi Komt Sings DESIGNATION: Junior Engineer