FIELD INSPECTION REPORT

In			CIELD MOTE	ECTION REPORT		
D	ate	of Inspection : /	7.12.20	District: East dampe	Cont. 1.1	
N	1V151	on: Rarau			70000	
Sc	hem	of the Road: Zo	MAINTENANCE	Good Tale	e definition and an extension of the ext	
Pa	ckag	ge No.:	MAINTENANCE	MMUSY (WIB)	nd er in religionis propriessos analysis in include and in-	
Sta	itus	of the Project:	Owner	Road Id No.: 317685	17011	
Wo	Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
SI.	No.			THE RESERVE OF THE PARTY OF THE		
1	1,	Parameters to be checked Pavement			Remarks	
a)			to a constitution of the c		
b		Road Junction condition			V5/U	
		Condition of Surfacing			\$10	
(c)		Riding Quality			√S/U	
d)		Road Camber		-	Sru	
c)		Whether free taggregates in case	from defects such e of CC Pavement.	as visible cracks, expose	d Yes/No	
l)			s provided or not (CC	Pavement)	Yes/No	
g)	1	Compaction of flank/slope & raincuts if any				
2.	- 1	Cross Drainage Yes/No				
a)			malla in the		-	
b)	-	Condition of head	on of head walls in Hume pipe culverts including its painting			
	wans, 51ab			S/SRI/U		
c)	1		gs/slab/approach for B	ridges	N,S/SRI/U	
3,	3. Road Furniture					
a)	sto	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Co	mpliance Histor	y			
a)	Sta	lus of ATR's & a	ny others		N.A.	
					1 - 3	

Overall Rating

Satisfactory (S)	101
Satisfactory but requires Improvement (SRI)	3
Unsatisfactory (U)	

(Signature)

NAME: Saujay Komar DESIGNATION: A.E., Raxauf