

FIELD INSPECTION REPORT

mm (sc)

Date of Inspection :	25.12.20	District:	Sermastipur
Division :	Sermastipur	Length (km):	0.720
Name of the Road:	L027 Hansapur to Pokhas Tah		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	320/01/3056
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No✓
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Geetam Das

J.E.

25.12.20
(Signature)