

FIELD INSPECTION REPORT

Date of Inspection: 15/12/2020		District: SAMASTIPUR	
Division: SAMASTIPUR		Length (km): 1.010	
Name of the Road: 624 Chak Labib to harjan tola ward no. 11			
Scheme/Programme: MAINTENANCE		MMGSY (SC)	
Package No.:		Road Id No.:	
Status of the Project:		Being/Completed/Under Maintenance	
Work is a case of:		Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	
a)	Road Junction Condition	S/U	
b)	Condition of Surface	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of Slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & others	NR	

Overall Rating :

Satisfactory (S)	U
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: SRAVAN KR. SINGH

SRAVAN
24.12.20
(Signature)