

FIELD INSPECTION REPORT

Date of Inspection : 05.12.2020		District: SAMASTIPUR
Division : SAMASTIPUR		Length (km): 0.340 km
Name of the Road: To 2 Mohapur N.H. to west to a via Subjimanoli		
Scheme/Programme: MAINTENANCE		
Package No.: MMGSY (SC)		
Status of the Project:		Road Id No.:
Work is a case of:		Going/Completed/Under Maintenance
		Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joint provided or not (CC Pavement)	Yes/No
g)	Compaction of Slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards, Informatory/cautionary Board/km & 200m markings are provided and maintained	Yes/No
4.	Compliance His	
a)	Status of ATR's & others	NIL

Overall Rating :

Satisfactory (S)	U
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature
26.12.20

NAME: GRAVAN KR. SINGH