## FIELD INSPECTION REPORT

Date of	Inspection :	28-12-2020 District:	Samastipur	
Division: Paton Length (km):  Name of the Road: Any way day Karryalay Paton to O			andum	
	the second secon	numandal karyalar	parton 10 G	na je utom
Scheme/Programme: MAINTENANCE Road Id No.:				
rackage 100.		Property I		
	f the Project:	New Connectivity/Up gradation		lainter
		Parameters to be checked	是一种社会的证据 法所以的特别的 计数字字段	Remarks
Sl. No.	Pavement			
San Carried	in the second second second			SUN
a)	Road Junction	Road Junction condition		S/J
b)	Condition of Surfacing			S/J
c)	Riding Quality			S/U S
d)	Road Camber			S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No Yes/No /
f)	Contraction Joints provided or not (CC Pavement)			Yes/N6
(g)	Compaction of flank/slope & raincuts if any			TXS.No /
2.	Cross Drain	nge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U S	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U- S	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/Ne-
4.	Compliance History			7
a)	Status of ATR's & any others			NIA
Overall	Pating			N/A
Ovciali	ramig :	Satisfactory (S)	<del></del>	0
		Satisfactory but requires Im Unsatisfactory (U)	provement (SRI)	

NAME: AJay Kuman Lingh

DESIGNATION: J. E.

Scanned with CamScanner

2.8/19/2020 (Signature)