

FIELD INSPECTION REPORT

Date of Inspection : 3-1-2021	District: Chay 4
Division : R.W.D. Chaya	Length (km): 2.872
Name of the Road: L 668 Chakand Mandol Road to Simarziya	
Scheme/Programme: MAINTENANCE	PMGSY Scheme
Package No.: BR 12 R 677	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: ✓	New Connectivity/Up gradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Culverts	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Markings	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
b)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Signboard painting as well as Culvert Head wall painting required.

Ch
03/01/2021

(Signature)

NAME
DISTRICT

Ghanshyam Patil Pankaj
E.E. RWD Chaya