

FIELD INSPECTION REPORT

Date of Inspection : 31-12-2020	District: Gaya
Division : R.W.D. Gaya	Length (km): 1.352
Name of the Road: LDEI - Gaya Sherghati Road To Rehua	
Scheme/Programme: MAINTENANCE	P.M.U. 57
Package No.: BR12R 680	Road Id No.:
Status of the Project: ☒ Ongoing/ ☒ Completed/ ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	8/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

Ashish Kumar Mondal

A.E., Gaya Nagar

(Signature)

31-12-20