

FIELD INSPECTION REPORT

Date of Inspection : 31-12-2020		District: Gaya
Division : R.W.D. Gaya		Length (km): 0.891
Name of the Road: 1032 Gaya Sheergathi Road To 5th Cr. N.		
Scheme/Programme: MAINTENANCE P.M.U.S.		
Package No.: BR 12 R 631		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		✓
Work is a case of: New Connectivity/Up-gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

A.E. 31-12-2020
(Signature)

NAME: Aishwarya Kumar Mahto

DESIGNATION: A.E. Gaya Nagar