FIELD INSPECTION REPORT

	nspection: 3)-12-20 District: Cray a	
Division	Length (km) 1 mg/	
Name of	the Road: Lo 64 Clayer Dobbi Part to Rola	Li.
	rrogramme: MAINTENANCE P.O. A. L. 4	
Ctatus of	No.: BR 12R 683 Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up and attenue.		
Sl. No.		Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	∠ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	∕ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	as a final median is work subject that the things is regarded by
b)*	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U /
c)	Condition of railings/slab/approach for Bridges	S/SRI/U A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
8)	Status of ATR's & any others	N'A

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: AIRN FER IRAM EMANDER!

DESIGNATION: A.E. Liega Nogo