

FIELD INSPECTION REPORT

Date of Inspection : 31-12-20	District: Gaya
Division : R.W.D. Gaya	Length (km): 0.571
Name of the Road: L 066 Chaturghat macdarghose to Se Tala	
Scheme/Programme: MAINTENANCE	P. m. 1-54
Package No.: BR 12 R 6 85	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ✓
Work is a case of: ✓	New Connectivity/Up gradation/ Maintenance

hallargh
(VR 6)

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Akshay
31-12-20
(Signature)

NAME: Akshay Kumar Mondal

DESIGNATION: A.E. R.W.D. Gaya Nagar