## FIELD INSPECTION REPORT

Date of Inspection: 25/12/2010			District: Purnea	
Division : Purnea			Length (Km): 3 - 773	
		46 Jageli leich tole	Dr.	
Scheme/	Programme:	Maintenance		
Package	No.:		Road ID No. :	
Status of the Project : Ongoing/Completed/Unc			er Maintenance	
		New Connectivity/Up gradation/Maintenance		
		Parameters to be Cheel	The state of the s	Remarks
1).	Pavement			
a)	Road Junction condition			S/U ~
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			✓\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			√Fes/No
f)	Contraction Joints provided or not (CC Pavement)			¥es/No
g)	Compaction of Flank/Slope & Raincuts if any			Yes/No~
2).	Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U MP
c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U MA
3).	Road Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No
4).	Compliance History			
a)	Status of ATR's	& any others		
Overall	Rating :	Satisfactory (S)		
Overall	Nating .	Satisfactory but requires Imp	rovement (SRI)	
		Unsatisfactory (U)		U
		Unsatisfactory (0)		0.

(Signature)

Name: ROHA SALMAN

Degisnation: 15%

RWD, Works Division, Purnea.