


FIELD INSPECTION REPORT

Date of Inspection : 25/12/2020		District : Purnea	
Division : Purnea		Length (Km) :	
Name of the Road : LO45 kaurbari to oraila ghat masjid Tola			
Scheme/Programme :		Maintenance	
Package No. :		Road ID No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No	Parameters to be Checked		Remarks
1). Pavement			
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of Flank/Slope & Raincuts if any		Yes/No
2). Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/UNA
3). Road Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		✓Yes/No
4). Compliance History			
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	

Name : ROMA SARKAR
 Designation : J.E


 25/12/20
 (Signature)