FIELD INSPECTION REPORT

hate of la	ispection: 03	1501 021	District: Katihan	11.44	
Division: Barso è			Length (km): 1.80 km		
Vame of			kismat bari (BR-16R-3)	38)	
Scheme/l	rogramme:	MAINTENANCE			
4.1	No.: BR-16	R-338	Road Id No.:	21	
Status of the Project:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
Orac ordered by	n case of:		The second secon	1.46 Description	
Sl. No.		Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction condition		~57U		
b)	Condition of Surfacing			V8/1 U	
c)	Riding Quality			√81 Ú	
d)	Road Camber			√ \$/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting		√8/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		√5/SRI/U		
c)	Condition of	railings/slab/approac	h for Bridges	S/SRI/U	
3.	Road Furni	lure			
a)	Whether sig	n boards/informator, nent road markings at	y/cautionary Board/km & 200m re provided and maintained	Yes/No	

Overall Rating

4.

- 484.

Satisfactory (S)	15
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Mandsh chandra Anya

Compliance History

Status of ATR's & any others

DESIGNATION: TENG