FIELD INSPECTION REPORT

			4		
Date of	f Inspection: 31	12/2020	District: Kislagus		
Divisio	n: Kiflowgin	1-2	Length(km): 0.600 km		
Name	of the Road: PM	TIMEY Road	to uttar tota		
	e/Programme:	HTSNY			
Packag			Road Id No.: 21205818638		
	of the Project:	Ongoing/Comp	leted /Under Maintenance		
	s a case of:	New Connectiv	ity/ Up gradation / Maintenance	Remarks	
S1. No	a cuse on	Parameter	s to be checked	Remarks	
1.	Pavement			(5/11	
a)	Road Junction Condition			V S/U	
b)	Condition of Surfacing			✓ S/U	
	Riding Quality			✓ S/U	
c)	D. J.Combor			S/U	
d)	Whether free fr	rom defects such	as visible cracks, exposed aggregates	Yes/No	
e)	in case of CC Pavement.			. 6. 121	
٤)	Contraction Joints Provided or not (CC Pavement)			√Yes/No	
f)	Compaction of flank / slope & rain cuts if any			/Yes/No	
g)	a Projecto				
2.	Condition of head walls in Hume pipe culverts including its Painting			√S/SRI/U	
a)	Condition of Head Walls in William RCC culverts Condition of Abutment & Wing walls, slab in RCC culverts			✓ S/SRI/U	
b)	Condition of Abuthlent & Wing transport Condition of railings/Slab/approach for Bridges			~ S/SRI/U	
c)					
3.	Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m		Yes/No		
a)	stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a)	Status of ATR's 8	any others			

Overall Rating:

	100
Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:Umesh Kumar Singh J.E, RWD ,Kishanganj