

FIELD INSPECTION REPORT

Date of Inspection : 29.12.20		District: East Chhappan	
Division : <u>Raxaul</u>		Length (km): 0.892	
Name of the Road: <u>Los2 - Los2 Smtiya Bait to Smtiya No 41 to Smtiya No 2</u>			
Scheme/Programme: <u>MAINTENANCE</u>		<u>PAYG5Y</u>	
Package No.: <u>BR-11K-644</u>		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1. Pavement			
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		✓Yes/No
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		N.A./S/SR/U
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary. Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No
4. Compliance History			
a)	Status of ATR's & any others		N.A.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Nillesh Kumar Singh

DESIGNATION: Junior Engineer, Raxaul

(Signature)

 29/12/20