

FIELD INSPECTION REPORT

Date of Inspection : 31/12/2020
 Division : Madhubani District: Madhubani
 Name of the Road: 104 to Kaithahi East Length (km): 3.494
 Scheme/Programme: MAINTENANCE
 Package No.: BR21R622 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U (Some patch)
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	Yes/No No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Partly maintained
4.	Compliance History	
a)	Status of ATR's & any others	(No ATR)

Overall Rating :

Satisfactory (S)	(Maintenance work ongoing)
Satisfactory but requires Improvement (SRI)	X SRI
Unsatisfactory (U)	X

NAME: ANISH KUMAR SINGH
 DESIGNATION: ASSISTANT ENGINEER

(Signature) 31/12/2020