## FILLD INSPECTION REPORT

Date of I	nspection: O	3-1-2021	District: Madhubani		
Division: Madhubani			Length (km): 7-420 KM		
Name of	the Road: Pa	ekki Road Tax	sami To Gram Hati Tol		
Scheme/	Programme:	MAINTENANCE			
Package No.:  Status of the Project: Ongoing/Comple			Road Id No.:		
			going/Completed/Under Maintenance w Connectivity/Up gradation/ Maintenance		
SL No.				Remarks	
1.	Pavement				
a)	Road Junction condition			S/U U	
b)	Condition of Surfacing			S/U U	
c)	Riding Quality			s/u <b>u</b>	
d)	Road Camber			S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No N	
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No Y	
g)	Compaction of flank/slope & raincuts if any			Yes/No )	
1.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Kond Furnitus				
<b>a</b> )	stones/Pavement road markings are provided and maintained			Yes/No	
	Compliance History			*************************************	
a)	Status of ATR's & any others			<u> </u>	
A					
Overall	L'antrig	Satisfactory (S			
and the second	a there are the	Satisfactory b	ut requires Improvement (SRI)		

(Signature)

NAME: Md. Manowar Jehny DESIGNATION: JE fandaul.