FIELD INSPECTION REPORT

Dat	te of Ir	aspection: 29/12	120 District: APEET2		
Name of Road: Scheme/ Programme:			2038 से पीखर टीजा		
			MAINTENANCE MML787 (ST)		
Pa	ckage	No.	Road ID No.		
Status of the Project:			Onging/Completed/Under Maintenance		
Work is a case of:			New Connectivity/ Up Gradation/ Maintenance		
100	SLNO.	- 100 to 2	Parameters to be Checked	Remarks	
1	1	Pavement			
Г	a)	Road Junction Cone	dition	S/U	
	b)	Condition of Surfacing S/			
1	c)	Riding Quality S/U			
-	d)	Road Camber S/U			
-	e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			
1	f)	Contraction Joints provided or not (CC Pavement)			
1	g)	Compaction of flank/slpoe & raincuts if any Yes/No			
	2	Cross Drainage			
F	a)	Condition of head	ondition of headwalls inn Humepipe culverts including its painting		
1	b)	Condition of Abutment & Wings walls, Slab in RCC culverts S/SRI/U F			
1	c)	Condition of railings/slabs//approach for Bridges S/SRI/U			
1	. 3	Road Furniture			
	a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			
	A	Compliance History			
	a)	Status of ATR & any others			
Overall Grading:			Satisfactory (S)	3-	
			Satisfactory but requires Improvement(SRI)		
			Unsatisfactory (U)		

Name: Landbalandra Lam.
Degisnation Junior Engèneu

(Signature) (Signature)