

FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020	District: Pune
Division : R.W.D. Div - Pune	Length (km): 1.270
Name of the Road: Sal Rodasig Bagad part to gonkhali 70	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	LSU
b)	Condition of Surfacing	LSU
c)	Riding Quality	LSU
d)	Road Camber	LSU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No SRI
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/LSU SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	LS/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Munilal Day
18/12/2020
(Signature) J.E

NAME: