## FIELD INSPECTION REPORT

		28/12/20	District: Machelan	
Division: Jainger			Length (km): O.60	
		bubarki Rajnege	PND fred & calum.	waiya th
	Programme:	MAINTENANCE	Road Id No.:	
		Ongoing/Completed/	empleted/Under Maintenance	
		New Connectivity/Up gradation/ Maintenance		
SI. No.	A STANDARD CONTRACTOR	Parameters to l		Remarks
1.	Pavement			
a)	Road Junction condition			<b>∨</b> S/U
b)	Condition of Surfacing			<b>⊳</b> S/U
c)	Riding Quality			S/U
d)	Road Camber			/s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b) -	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitu	ie:		Maria Americana de las
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance 1	a mayor and an area for the contract of the co		10 10 10 10 10 10 10 10 10 10 10 10 10 1

Overall Rating

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	SRC.
Unsatisfactory (U)	

NO

NAME: Siles Kr. Jumen:
DESIGNATION: 16

Status of ATR's & any others