FIELD INSPECTION REPORT

Name of Road: Scheme/ Programme:		LO38 32RA MAINTENANCE GZTSNY	
Status of the Project: Work is a case of:		Onging/Completed/Under Maintenance New Connectivity/ Up Gradation/ Maintenance	
*	Pavement		
a)	Road Junction Condition S/U		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		~S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slpoe & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting		S/SRI/U the
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U H
c)	Condition of railings/slabs//approach for Bridges		S/SRI/U
-3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No
A	Compliance History		
a)	Status of ATR & any others		HA
Overall Grading:		Satisfactory (S)	5-
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: Ramchandre Ram.
Degisnation Tunion Enfineur

(Signature)