FIELD INSPECTION REPORT

Date of	Inspection: 0.	10 /2020	District: Rishanghone		
Date of Inspection: 31/12/2010 Division: Rishangany -1			Length(km): 1.000 1cm		
Name o	f the Road:	g I	atalwa		
	/Programme:		gawa		
Package		GTSNY	Road Id No.: 21205801841		
	of the Project:	Ongoing/Compl	eted /Under Maintenance		
		0 0.			
Work is a case of:		New Connectivity/ Up gradation / Maintenance Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction Condition			√ S/U	
b)	Condition of Surfacing			✓ S/U	
c)	Riding Quality			√ S/U	
d)	Road Camber			V S/U	
e)				Yes/No	
<i>C</i>)	in case of CC Pa		as visible cracks, exposed aggregates		
f)				Ves/No	
g)	Compaction of flank / slope & rain cuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			VS/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			VS/SRI/U	
3.	Road Furniture				
a)	Whether sign b	oards/informator	ry/cautionary Board/km & 200m	Yes/No	
	stones/Paveme	ent road markings	are provided and maintained		
4.	Compliance His	story			
a)	Status of ATR's	& any others			

Overall Rating:

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:Umesh Kumar Singh J.E, RWD ,Kishanganj