FIELD INSPECTION REPORT

ate of In	spection: 29/12	1/20	District: SPET		
			То2 मजी 6 मोलबी वे खुरहा टोला		
scheme/ Programme: MAIN		MAINTEN	AINTENANCE GITSNY		
Package No.			Road ID No.		
Status of the Project: Ongi		Onging/Cor	nging/Completed/Under Maintenance		
	Work is a case of:		New Connectivity/ Up Gradation/ Maintenance		
SLNO	Andreas Andreas Park	Para	meters to be Checked	Remarks	
Shiso	Pavement	74. 1. 10. 1			
	Road Junction Condition			S/U	
a)	Condition of Surfacing			S/U	
b)	Riding Quality			· S/U	
c)	Pood Camber			S/U	
(e)	Whether free from defects such as visible cracks, exposed aggregates in case of			Yes/No	
-	CC Pavement Contraction Joints provided or not (CC Pavement)			Yes/No	
f)	Compaction of flank/slpoe & raincuts if any Yes/N			Yes/No	
g)					
2	Cross Drainage Condition of headwalls inn Humepipe culverts including its painting			-S/SRI/U	
a)	Condition of Abutment & Wings walls, Slab in RCC culverts			S/SRI/U P	
b)	Condition of railings/slabs//approach for Bridges			S/SRI/U	
c)	Read Farniture				
a)				Yes/No	
A		Compliance History			
a)	Status of ATR & any others				
Se Se		Satisfactor Satisfactor Unsatisfac	ry but requires Improvement(SRI)	2	

Name: Ramchanda Ram Degisnation Junior Enférior (Signature)