FIELD INSPECTION REPORT

Date of I	nspection:	26 20 12 Distri	District : Purnea	
Division	: Purnea		Length (Km): 1.300	
Name of	the Road: Lo	34 Se to Flangari -	tola	
Scheme/	Programme:	Maintenance		
Package	No.:	Road	ID No.:	
Status of the Project: Ongoing/Completed/Under N			ınce	
Work is a case of: New Connectivity		New Connectivity/Up gradation/Main	Up gradation/Maintenance	
Sl. No		Parameters to be Checked		Remarks
1).	Pavement			
a)	Road Junction	condition	\\$1 U	
b)	Condition of Surfacing			SFU
c)	Riding Quality			S/U
d)	Road Camber			YS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of Flank/Slope & Raincuts if any			Yes/No
2).	Cross Drainage			
a)	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U NA	
c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U NA
3).	Road Furniture			
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		Yes/No	
4).	Compliance History			
a)	Status of ATR's & any others			
Overall l	Rating :	Satisfactory (S) Satisfactory but requires Improve	ment (SRI)	SRI
		Unsatisfactory (U)		

Name: ROMASARRAR

Degisnation: 18

RWD, Works Division, Purnea.

26/12/2020

(Signature)