


FIELD INSPECTION REPORT

Date of Inspection: 31/12/2020		District: Kishanganj
Division: Kishanganj - 2		Length(km): 1.000 km
Name of the Road: DMSBY to Malhana		
Scheme/Programme: B.TSNY		
Package No.:		Road Id No.: 2120581830
Status of the Project:		Ongoing/Completed /Under Maintenance
Work is a case of:		New Connectivity/ Up gradation / Maintenance
S1. No	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No
g)	Compaction of flank / slope & rain cuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	[S]
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature) 31/12/20

NAME: Umesh Kumar Singh
J.E, RWD ,Kishanganj