FIELD INSPECTION REPORT

Date of	Inspection: 31	12/2020	District: Kighangang	
Division	1: Wishangar	y -1	Length(km): 1.000 km	
	- (1	PMUSY to Di	anger Tola	
Scheme	e/Programme:	4 TSNY	0	
Package	e No.:	,	Road Id No.: 21205861833	}
Status of the Project:		Ongoing/Completed /Under Maintenance		
Work is	a case of:	New Connectivi	ty/ Up gradation / Maintenance	
S1. No		Parameters	s to be checked	Remarks
1.	Pavement			
a)	Road Junction Condition			V S/U
b)	Condition of Surfacing			V S/U
c)	Riding Quality			✓ S/U
d)	Road Camber			V S/U
e)	Whether free from defects such as visible cracks, exposed aggregates			
	in case of CC Pavement.			
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No
g)	Compaction of flank / slope & rain cuts if any			Yes/No
2.	Cross Drainage	2		
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign b	ooards/informato	ry/cautionary Board/km & 200m	₩es/No
	stones/Paveme	ent road markings	are provided and maintained	
4.	Compliance His	story		
a)	Status of ATR's	& any others		

Overall Rating:

Satisfactory (S)	(5)	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME:Umesh Kumar Singh J.E, RWD ,Kishanganj