## FIELD INSPECTION REPORT

Jate of	Inspection:	7-112-2020	District: Samutipuz	
Division: Paton			Length (km):	
	f the Road:	Jospula C	have to Manche Si	and a
	Programme:	MAINTENANCE	Read Id No.:	
ackage No.: tatus of the Project: Ongoing/Comple		T Onnaina Cample	ted/Under Maintenance	
	a case of:			1M954
W 1	a case or:	1	to be checked	Remarks
a. No.		Parameters	to be checked	1 1 1 2
4.	Pavement			
a)	Road Junction condition			SA
b)	Condition of Surfacing			S/U
c)	Riding Quality			SAY
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
1	Cross Drainage			
2)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRIJU
c)	Condition of railings/slab/approach for Bridges			S/SRIAU-
3.	Road Furniture			
<b>a</b> )	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			N/A

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: AJ on by bright DESIGNATION: J. G