HELD INSPECTION REPORT

Date of	Inspection: 0	3-01-2021		
Division: Madhubani Length (km): 1.670 km.				
Schome o	the Road: Mc	MIMPUY GAOM	PMUSY Road Urdu Maktas	To Pana
Scheme/Programme: MAINTENANCE Package No.: Road Id No.:			Pond Id No.	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintelrance		
SL No.	e e en lambagada de de Transporta	Parameters t	o be checked	Remarks
1,	Pavement			
a)	Road Junction condition			S/U V
b)	Condition of Surfacing			S/U V
c)	Riding Quality			S/U V
d)	Road Camber			S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No 3
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No '
g)	Compaction of flank/slope & raincuts if any			Yes/No
L	Cross Drainage			
r)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
i)	Condition of Abutraent & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
•	Road Parniture			
a)	siones ravement road markings are provided and maintained			Yes/No
1/2/2	Compilates History.			= 7 (3)
a)	Status of ATR's & any others			
Overall	Rating :			*****
7.		Satisfactory (S)		_
And the first of t	THE STATE OF		t requires Improvement (SRI)	
are no del constitución del constitución del constitución del constitución del constitución del constitución d Constitución del constitución d		Unsatisfactory	(U)	U

03-01-2024 (Signature)

NAME: ASINE Proceed SI-86

DESIGNATION: PE pandow