

# FIELD INSPECTION REPORT

Date of Inspection : 17.12.20		District: East Champaran	
Division : Raxaul		Length (km): 1.152	
Name of the Road: Sacnada chaur to Nalaa Tola			
Scheme/Programme: MAINTENANCE		030454	
Package No.:			
Status of the Project:		Road Id No.: 31708561253	
Work is a case of:		Ongoing/Completed/Under Maintenance	
		New Connectivity/Up gradation/ Maintenance	
Sl.No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		✓/N
c)	Riding Quality		✓/N
d)	Road Camber		✓/N
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓/N
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N/A
g)	Compaction of Blank/slope & raincuts if any		Yes/No N/A
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓/S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓/S/SR/U
c)	Condition of railings/slab/approach for Bridges		✓/S/SR/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary. Board/km & 200m stones/Pavement road markings are provided and maintained		✓/Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		1 No. ATR Pending

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	SRT

NAME: *Atikilash Kumar Singh*  
 DESIGNATION: *Junior Engineer, Raxaul*  
*17.12.20*  
 (Signature)