## FIELD INSPECTION REPORT

ame of Road:		MAINTENANCE NABARD	
tatus of the Project:  Vork is a case of:		Onging/Completed/Under Maintenance  New Connectivity/ Up Gradation/ Maintenance	
SkNo	Pavement	CARROLL TO THE PARTY OF THE PAR	
a)	Road Junction Cond	dition	S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		\S/U
d)	Road Camber		VS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Wes/No
g)	Compaction of flank/slpoe & raincuts if any		Yes/No
2	Cross Brainage		1
a)	Condition of headwalls inn Humepipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slabs//approach for Bridges		S/SRI/U
- 3	Pand Empiture	The Allerton State of	State de
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No
4	The state of the s		TO THE REAL PROPERTY.
a)	Status of ATR & any others		MA
Overall Grading:		Satisfactory (S)	
		Satisfactory but requires Improvement(SRI)	SRI
		Unsatisfactory (U)	

Name: Ramchandser land Degisnation Turner Englisher

Scanned with Camsca