

FIELD INSPECTION REPORT

Date of Inspection :	24/12/2020	District:	Madhubani
Division :	Madhubani	Length (km):	1.011 km
Name of the Road:	Main hawari Tol Khaima Rajnagar REO Path to Barhara Dakkhila		
Scheme/Programme:	MAINTENANCE REO pitch Kati Asthan		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	(S/U
b)	Condition of Surfacing	(S/U
c)	Riding Quality	(S/U
d)	Road Camber	(S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	(Yes/No
f)	Contraction Joints provided or not (CC Pavement)	(Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No raincuts
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	(S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	(S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	(S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	(Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	X

(Signature)

NAME: ANISH KUMAR SINGH

DESIGNATION: ASSISTANT ENGINEER