

FIELD INSPECTION REPORT

old pmgsy

Date of Inspection: 4/01/2021 District: Bhojpur
 Division: R.W. 3 Dargahpur Length (km): 3.295 km
 Name of the Road: Lo2, Behiya chaurasta To Narayanpur (VR2)
 Scheme/Programme: MAINTENANCE
 Package No.: BR 07 R-223 Road Id No.: 10401702031
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance under maintenance

Sl. No. Parameters to be checked Remarks

1. Pavement

a) Road Junction condition S/U 3

b) Condition of Surfacing S/U 3

c) Riding Quality S/U 5

d) Road Camber S/U 3

e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No yes

f) Contraction Joints provided or not (CC Pavement) Yes/No

g) Compaction of flank/slope & raincuts if any Yes/No yes

2. Cross Drainage

a) Condition of head walls in Hume pipe culverts including its painting S/SRI/U 3

b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U 3

c) Condition of railings/slab/approach for Bridges S/SRI/U 3

3. Road Furniture

a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No yes

4. Compliance History

a) Status of ATR's & any others NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

4/01/2021
 PC

4/01/2021
 (Signature) PE